

## Summary of changes RAY17

---

### Version 1.2

---

2013-04-12

- Fixed bugs:
  - Actual output power name changed to rfCurPower.

### Version 1.1

---

2013-04-04

- New features:
  - New items: Station location; Link uptime; Current rf power; Service ethernet
- Fixed bugs:
  - Negative radio and modem temperatures fixed.
  - Time values coded as TimeTicks fixed.

### Version 1.0

---

2013-01-29

- New features:
  - Universal MIB file for RAY product line